

TO THE PROPERTY OF THE PROPERT



Arranging For New Cars From the Factories For El Pasoans

Many Dealers Are Visiting the Eastern Factories Making Arrangements for Early Deliveries or for Renewal of Existing Contracts; Numerous Car Sales Are Reported.

ONSONANT with the growth of El Paso, the demand for automobiles has grown. In order to meet the emand for cars, local men who have he agency for different makes of cars demand for cars, local men who have the agency for different makes of cars have ben paying visits to the manufacturers. The purpose of the visits was to renew contracts and to secure as early deliveries from the manufacturers

sarly deliveries from the manufacturers as possible.

T. M. Richardson, who has the Stude-baker agency, has wired that the manufacturers of those cars have assured him of early deliveries. Local respresentatives say that there will be plenty of 1914 Studebakers in El Paso. There will be no change found in the recent models. The 1914 car has been out four or five months, and the cars now being mainfactured are of the same model. Mr. Richardson left for Detroit, Mich., where the Studebaker is made, in June, He is expected to return Sunday.

J. W. Stockard, of the International Motor Car company, who has also spent two weeks in Detroit, looking over the automobile field, is expected back Monday or Tuesday.

F. L. Cox. of Silver City, N. M., was a visitor in El Paso. Mr. Cox made the trip in his Buick roadster. No car trouble of any character was experienced en route. He left Friday on the

Dr. Frank W. Lynoh is driving an Overland roadster. It is gray with black lines, and looks like a brand new car. The doctor had the car completely overhauled at the Two Repub-

pletely overhauled at the Two Republics garage, repainted, new lamps put on and other new fixtures added. He says the car runs better than it did when he first bought it.

The Longwell Auto & Truck Sales company, which has taken over the Overland agency, is moving the stock from its present location in the Southwestern building to the sales company's headquarters 122 San Francisco pany's headquarters, 122 San Francisco street.

Promoter Eddie Mowery, of the Albuquerque. N. M. outo races, to be run on Labor day, is trying to get Billy Adolph and his Studebaker "Betsy" to enter the 25-mile event to be staged at Traction park. The racing car is always

Dr. J. W. Ketchersid sold his Ford automobile this week to J. W. King of the El Paso Milling company. He will buy a new Overland.

Williams is in town on his second trip and upon his return to Dallas, is going to have shipped to El Paso three and five ton Peerless motor trucks. The cars will be sent to the local Chalmers Metor company.

Ernest Elisworth who grows plumes on ostriches down on the Southwest-ern ostrich farm on the county road, is now making his trips to town in a

five passenger Pope.

A five passenger Cadillac for the U.

S. Reclamation service was another machine that drew a number in the county clerk's office this week. H. S. Bozarth and W. G. Hadlock both registered for five passenger Fords.

Charles F. Invis out that the county clerk's passenger for the passenger for the passenger fords. istered for five passenger Fords. Charles F. Davis got a two passenger

GOOD ROADS BIG VALUE TO FARMERS

They Enable Farmers to Move Their Crops at Any Time, Not Merely When the Weather Is Good. Washington, D. C. Aug. 2,-How

when the Wenther is Good.

Washington, D. C., Aug. 2.—How states and countiles are putting money in the pockets of the farmers by intered in a race. If the inducements are sufficient, Adolph will go to Albuquerque with "Betsy."

A carload of Studebakers were on the siding Friday. The cars consisted of two "25's." two "35's" and two "6's."

They will be taken out of the car and placed in the salesroom on San Antonio street. O. H. Baum has six Hupmobiles on the road, and of them sold before they get here.

Professor Badenock, of the state college, Mesilla, N. M. was a visitor in El. Paso this week. He drove home in a Studebaker "25."

Fire marshal Henry Reynaud this week made a visit of all the local headquarters in the city. No fault was found with any. The fire marshal complimented the Studebaker and Chalmers people on the cleanilness of their shop.

Dr. J. W. Ketchersid sold his Ford automobile this week to J. W. King of the El Paso Milling company. He will

the prices.

Excessive fluctuations in market

Excessive fluctuations in market buy a new Overland,
buy a new Overland,

* * * *

Fay Sperry, of Las Cruces, N. M.,
made the trip to El Paso in a five-passenger Stanley stemmer. He arrived
Saturday morning. Mr. Sperry will
spend several days here. His car is at
the Cleveland Square garage.

* * *

Monday morning Charles Lowe, in an
Chearland "45," is going to Pearson, acwho has rel
who has rel
kets.

tion. They
gions where the local production.
There are counties rich in agricultural
possibilities, burdened with bad roads,
where the annual consumption.
There are counties rich in agricultural
possibilities, burdened with bad roads,
where the annual consumption.
There are counties rich in agricultural
possibilities, burdened with bad roads,
where the annual consumption.
There are counties, burdened with bad roads,
where the annual consumption.
There are recounties rich in agricultural
possibilities, burdened with bad roads,
where the annual consumption.
There are counties, burdened with bad roads,
where the annual consumption.
There are counties, rich in agricultural
possibilities, burdened with bad roads,
where the annual consumption.
There are counties rich in agricultural
possibilities, burdened with bad roads,
where the annual consumption.
There are counties rich in agricultural
possibilities, burdened with bad roads,
where the annual consumption.
There are counties rich in agricultural
possibilities, burdened with bad roads,
where the annual consumption.
There are counties rich in agricultural
possibilities, burdened with bad roads,
where the annual consumption. prices are seldom due to over-produc-tion. They frequently take place in re-gions where the local production does not equal the annual consumption.

MOTOR TURNS 3000 TIMES IN MINUTE

That an automobile motor can be made to turn at the almost incredible speed of more than 3000 revolutions per minute has been definitely established by the automobile testing plant of the Worcester Polytechnic institute. In fact, the motor on which these tests were made did even better than this supposedly unattainable figure, registering 3510 revolutions and doing it under conditions approximating as nearly as possible actual duty on the road.

Frederic J. Bushin's "American Gov-As long as they tast, copies of Frederic J. Haskin's great book, "The American Government," may be had at The Herald office. Present clipping of this paragraph and 60 cents. By mail, 15 cents additional.—Advertisement.

\$1875

MOTORISTS' PROBLEMS ARE SOLVED HERE

By WILLIAM H. STEWART, Jr.

is not too rich. The Indication of my motor is perfect. I believe the trouble is due to faulty design. Can you suggest anything that will help me?—John Hewther.

should open toward the rear so as to let the hot air out. This will improve the cooling facilities of your motor.

Motoring Department, The Herald—
The steering gear of my car squeaks, and upon investigation I find that the noise comes from inside the bottom of the steering post. Please advise me what to do?—Inex Roeyer.

The squeak in the housing of your steering post is due to a leak of lubrication. Remove the plug and pack the housing with greuse, and you will find that your trouble has been cured. Motoring Department, The Herald— In the change of rear springs from three-fourths elliptic to elliptic is it necessary to use radius rods?—Frank-

In Dorset.

It is perfectly practical to take the drive through the springs if you so desire as long as the springs are anchored to the frame. If, however, you wish to have shackles in each end of the spring, radius rods will be neces-

Motoring Department, The Herald—
So as to reduce carbon deposits to a
minimum, please advise what is the
lowest flash point of oil that should
be used on an automobile motor of
1,200 maximum revolutions?—S. P. W.
The proper flash point should be
about 400 to 450 degrees Fahrenheit.
Would, however, suggest that you write
the manufacturers of your car in order the manufacturers of your car in order to get their view upon the matter, not only in regard to the flash point, but beand oil best adapted to their

Motoring Department, The Herald—
I have a car equipped with a
electric starter. In starting my motor,
the starter does not turn the motor
over as rapidly as it used to when I first got the car. I thought possibly that the battery was not fully charged, but, upon testing same, found it to be in excellent shape, as the electrolyte showed 1300 specific gravity. What do you suggest?—M. M. S.

It is well to remember that there is a considerable current required to crank an engine; some starting motors drawing as much as 100 amperes. A loose connection between the battery and starting motor will materially af-fect the amount of current which flows thus reducing the pulling power of the starter. Would suggest a careful ex-amination of the wiring to make sure that there are no loose connections nor short circuit.

mor short circuit.

** * *

Motoring Department, The Heraid—
My car runs rell on low, but when rutting it in high jumps and jerks. Sometimes after it has been running for a short time it gradually becomes all right; then again sometimes it dies down and stops.—J. A. Hargitt.

Error what of say it is probable.

From what for say it is probable that the spork hours in your motor are eether dirty ar out of adjustment are ecther dirty or out of adjustment or the carbureter is in poor order. A great many meters, however, do not run well at a riew rate of speed and only attain efficiency when well heated. Only dirt in the gaseline tank and pipe leading to the carbureter will cause the trouble you occurbe. Would auggest that you clean the entire gasoline system.

Motoring Department, The Herald— am troubled with my motor, which a 4 cylinder 4%x5, with exhanst valves in head and intake valves on side. The motor does not develop its proper power; have had the car-

CAMPAIGN AGAINST THE "JAYWALKERS"

Miss S. C. Geary, of Los Angeles, De-clares the Careless Pedestrian is a Mennee.

Los Angeles, Cal., Aug. 2.-Miss S. C.

Tell us of your experience for the sheefelow.

Correspondence invited for publication every Week-End.

Copyright, 1913, by W. H. Stewart, Jr.

Copyright, 1913, by W. H. Stewart, Jr.

Motoring Department, The Herald—I burster people adjust same with roots a bad in the common people with the process of the common people will be a bad in the common peop

Motoring Department. The Herald—The clutch on my car drags or silve, causing me no end of trouble. A change in the proportions of oil and kerosene in the clutch case results in a drag, while starting or silpping after the car has gone less than half a mile. Various proportions of oil and kerosene have been tried and the clutch has been flushed out repeatedly. Also have adjusted the clutch spring, but without success. What do you suggest to climinate this annoyance!—Reader. Unless a disc clutch is in good condition it will grip when starting the car. Usually this trouble can be overnowned by cleaning the disc, which should be done about twice a year. However, there are so many differently designed disc clutches in use flas nearly all have to has been to provide the clutch have been bent or buckled the trouble you mention may manifest itself. The multiple disc clutch when in good condition should have an equal amount of file-filed between each disc. It any of the discust are been or out of round the feroreoing will be impossible. The clutch spring should not be taken up more than three or four turns of the adjusting nut. eVur trouble could be hemeded by installing a new set of oronze discs.

Motoring Pepartment, The Herald—My car has given me considerable trouble was proportions which we impose that have a sense of not all any of the adjusting nut. eVur trouble could be hemeded by installing a new set of oronze discs.

Motoring Pepartment, The Herald—My car has given me considerable trouble was presented with by a ring of has less and the clutch spring should not be taken up more than three or four turns of the discs are bent or power of the clutch have been bent or out of round the feroreoing will be impossible. The clutch spring should not be taken up more than three or four turns of the distance of the clutch have a careful inspection of your spring should not be taken up more than three or four turns of the feroreoing will be impossible. The clutch spring should not be taken up more than three or four turns o

BUY AN AUTO AND DRIVE IT, ADVICE

That's What This Owner, Who Had Never Held Wheel, Did-Npt Hard Work.

For the benefit of those who, through lack of experience, may be deterred from owning and driving motor cars, Arthur S. Tullock, of Butte, Mont, comes forward with a unique experience

Bud Fisher, whose brain children. Mutt and Jeff, have delighted thousands of Herald resders in the past few years, has joined the ranks of motoring carteonists. Fisher's choice is a Loster light six, which he purchased from Harry S. Houpt, New York dealer for the Lozier company. Fisher's originality found expression both in the way his car is decorated and the manner in which it was shipped from the factory at Detroit. So anxious was the carteonist to receive his machine that he ordered it sent by express, Once it arrived in the "Big Town," the newspaper artist tried his hand at mural decorating on the two rear doors of the car. A small miniature of Mutt now adorns one tonneau door, with a counter portrait of Jeff on the other door. Thus will the car announcer at the theaters recognize the Fisher family when they arrive to put on their act.

We can sell you sast, doors at panel door prices. Lander Lumber Co. Ad-vertisement. Motoring Department. The Herald—My car has given me considerable trouble by overheating this summer. I have cleaned the radiator and water fackets and installed a new pump and hose contection. The fan works properly and the mixture of the carburetor is not too rich. The lubrication of my motor is perfect. I believe the trouble is due to faulty design. Can you suggest anything that will help me?—John Hewther. Would suggest that you cut gills or air vents in the sides of the hood which covers the engine. These vents should open toward the rear so as to let the hot air out. This will improve the cooling facilities of your motor. ** ** Motoring Department. The Herald—The action of valves sometimes is interfered with by a ring of hardened of life walve seating, and eccasionally holds the valve eff its seat for an instant if the stem is a triffe loose in the guide. The remedy by scraping off the deposit is obvious. It is not safe to assume that because there is nothing on the contact face of the valve and seat that all is well; there should be no deposit anywhere near the valve. It not frequently happens that the gummy stuff looks a good deal like the rough iron, but a touch with a scraper or screwdriver will show the difference. ** As most of spring breakage that oc-DIRECTORY AUTO FOR BIRE. PHONE L-Adcents additional.-Advertisement. 1914 (halmers

As most of spring breakage that occurs is due to loose spring clips, it is a pretty good idea to examine these parts especially after touring and to tighten them if necessary.

Leaky plugs can cause a lot of trouble that is very difficult to trace. They will make a motor miss at high speed or on heavy pulls, but will permit it to run quite properly, to all intents and purposes under ordinary conditions. The principal trouble is cracked or porous porcelains which allow the high tension current to ground without jumping the spark gaps. The only remedy is to fit new plugs that are known to be in good condition and to be careful not to crack the porcelains in tightening them in the cylinders.

The not uncommon habit that some drivers have of turning the steering wheel by short, quick jerks is not conducive either to good driving or to the wellfare of the steering gear. A steady, continuous wheel movement is not difficult to acquire with a little tractice. practice.

Anything that tends to push a vaive to one side, or lift it by applying force in any way except centrally, is liable to cause unequal and abnormal wear of both stem and seating. For this reason the end of the stem and the top of the lifter or tappet should be true and square and make perfectly even centact, which caunot be done if either is unevenly worn. This is a matter that often has made trouble and it has been ascribed to other causes.

* * * Many tire experts agree that more than half of the number of tire troubles are due directly or indirectly to underinflation. As it is, in the case of the pneumatic tire, not the rubber but the air which carries, suspends, and cushions the weight of the vehicle-everything of course, depends on having as much air as possible in the tire tube, without approaching the breaking point of the rubber at the weakest place of the tube. Every molecule of air which can be safely held in piace in the tube helps to do the work for which the air is employed. Incidentally, it keeps tube and casing in the most desirable form, for which they are designed, and holding them rigidly offers stones, nalls, and other road sundries such resistance as is needed to make the impact harmless. Many fire experts agree that more

CARE OF A TIRE; HOW TO SAVE IT


New tires carried on the side of the car, if not protected from the sunlight, will quickly oxidize, crack and become quite worthless.

A new tire should preferably be put into service a little while until the cover has been soiled. It will not then deteriorate nearly so quickly. It is better, however, to have a cover for extra tires.

Po not store them away in a warm place for any great length of time. Light or heat will cause the sulphur fo come to the surface and make the cover minutely porous. After this oxidation takes place, the nerve fiber of the rubber is destroyed and naturally the durability is greatly impaired.

A dark dry room, at a temperature of 40 to 50 degrees, is most favorable for retarding chemical action in the rubber and the "friction" stock on the fabric layers.

Automobile & Accessories



reer's Electric Garage 508 N. KANSAS Electric Cars, Sparking Batteries, and

Richardson Motor Car Co., Distributors.



E. P. & S. W. BUILDING COR, FRANKLIN AND N. STANTON C. P. HENRY, Manager.

Winton Six

El Paso Auto Sales Co. Office 713 N. Ochoa St. J. R. JOHNSON, JR., MGR.

Service Station

Remy Magnetos

Ignition and Lighting WISEMAN & ANDERSON, Ignition Specialists,



Longwell's Auto Truck & Sales Co. J. J. Longwell, Manager, 120-22 San Francisco St.

Overland Cars

Geo. L. Fisher, Distributor. Salesrooms Southwestern Building. P. O. Bex 77.

Jack Rabbit El Paso Rubber &



Automobiles Auto Supply Co.

Auto Painting

Auto & Carriage Painting & Trimming. Automobile Painting a Specialty. CHAS. E. BOSS. 700-706 Texas St. Phone 4033.

Vulcanizing Old Tires Made New. Tires and Tubes of all Makes Vulcanized and Repaired. Strictly First Class Work. Corner Missouri and Kansas Sts. Phone 6294.

Aber-Clements Auto Supply Co.

Lee Tires You Have Tried the Rest Now Try the BEST. 401 Myrtle St.

Mack & Saurer Trucks Built for Western Conditions Factory Branch-International Motor Co. 205 S. Santa Fe St., El Paso.

WESTERN MOTOR

FISK TIRES 406 San Francisco Street Phone 528,

SUPPLY CO. WRITE FOR CATALOGUE

CHALMERS MOTOR CO. OF EL PASO

Five-Passenger Touring Car Four-Passenger Torpedo

Fully equipped with Chalmers silk Mohair top, genuine rain-vision windshield, Chalmers

patented self-starter, Continental demountable rims, Warner Speedometer, Gray & Davis

full electric lighting system, with special new dash light; new design non-rattling tire

carrier, power tire inflater, horn, pump, jack, full set of tools, etc.

Cor. W. San Antonio and Santa Fe Sts.

No other car at the same price or near the

same price can compare with this car in value.

In addition to the superior long-stroke motor

-4 1-4"x5 1-4," the quiet, four-speed trans-

mission, and all the other noteworthy points

embodied in the previous model, this new

"Thirty-Six" offers many new and advanced

Molded Full Oval Fenders

practical European feature-add greatly to

the appearance. All-metal bodies, extra roomy,

with long, graceful lines, full flush sides and

bell backed tonneau make this car truly a

is on the rear. An accurate gasoline gauge is

provided. The tank is large-25 gallons-

and in its new position adds to the appearance

Clean Running Boards

and tool boxes being carried beneath the front

The running boards are clean—the battery

On the new "Thirty-Six" the gasoline tank

Molded full oval fenders-a popular and

features.

model for comfort.

and riding qualities of the car.

For proof of this, note the following facts:

El Paso, Texas

seats. Tires are carried in the rear over the

gasoline tank. The holders are absolutely non-

The new "Thirty-Six" is convenient, every

driving operation being controlled from the

A foot button operates the efficient Chal-

mers self-starter. One simple switch controls

the Gray & Davis lighting system. Carbu-

All Controls on Dash

horn and Warner speedometer are all on the

cowl dash. A new dash light illuminates all

ble drop frame is unusually heavy. Steering

connections are all drop forgings. Brakes are

will be convinced that no such value has ever

been embodied in another car at near our price

-\$1875 (fully equipped, f. o. b. El Paso).

See this new "THIRTY-SIX" and you

Ignition switch, gasoline pump, light meter,

The new car is designed for utmost strength and safety. Axles are of nickel steel, the dou-

rattling and self-locking.

retor is adjusted from the dash.

of maximum strength and power.

the control devices.